

Compostable Materials Handling Operation and Facility Inspection Report (93)

Enforcement Agency:		City of San Diego			
SWIS Facility File Number (99-xx-9999)		Inspection Date		Program Code	
37-AB-0003		4/20/2012		LEA Periodic	
Time In	10:20 AM	Time Out	1:10 PM	Inspection Time	2.9 hours
Facility Name			Received By		
Miramar Greenery			City Of San Diego, ESD		
Facility Location			Owner Name		
5180 Convoy Street, San Diego 92111			MCASM		
Inspector			Also Present (Name)		
Christina Buchanan			R. Tilaro, ESD		

THE ABOVE FACILITY WAS INSPECTED FOR COMPLIANCE WITH APPLICABLE SECTIONS OF THE DIVISION 30 OF THE PUBLIC RESOURCES CODE (PRC) AND TITLE 14 AND TITLE 27 CALIFORNIA CODE OF REGULATIONS (CCR)

X	No Violations or Areas of Concern	
V	A	Regulations
Inspection Report Comments:		
<p>Facility looked good during inspection. There were five windrows undergoing pathogen reduction in the Purple Zone. Temperatures measured in Rows 3 and 4 were 138F, 143F, 138F, 146F, 142F, 140F. Be sure temperatures are maintained at 131F or above for 15 days or more during the pathogen reduction process.</p> <p>The legacy stockpile of mulch has been cleared from the site. The area will be re-graded and then used as a repository for Alternative Daily Cover material for the landfill. About 2,000 cubic yards of material will be maintained in the area and the scraper trucks that deliver the material to the landfill will have their own ingress and egress roads so that the heavy equipment is maintained safely away from the Greenery traffic.</p> <p>Records for special occurrences, temperatures, and trash diverted to the landfill were reviewed.</p>		